



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Vernal Field Office
170 South 500 East
Vernal, Utah 84078-2799
<http://www.blm.gov/utah/vernal>

Phone: (435) 781-4400
Fax: (435) 781-4410

S/047/034

IN REPLY REFER TO:
3500
UT08300

April 11, 2001

Tony Gallegos
Division of Oil, Gas and Mining
1594 West North Temple Suite 2210
Box 145801
Salt Lake City, Utah 84114-5801

Dear Tony:

In January, I e-mailed you some information about my efforts to locate some of the features in the Horseshoe Bend area using a Trimble GeoExplorer 3 (GPS) datalogger. I recently returned to the area to record the location of one of the two roadways apparently constructed across public lands, apparently used to access the now inactive Yerian mine in T.7S., R.21E. Section 2. The purple lines on the enclosed figure shows the roadways I believe were constructed to provide access to the Yerian mine. They are about 1,350 feet in length.

Our office has no record of an authorization for the construction of these roadways. We would appreciate the Division making the reclamation of these two road segments an additional requirement of the operator of record to small mine permit S/047/034.

Please contact me if you have any questions.

Sincerely,

Pete Sokolosky
Geologist


enclosure

RECEIVED


APR 12 2001

DIVISION OF
OIL, GAS AND MINING

Two-track bladed roads gps'd April 10, 2001



- survey monuments
- ⬡ quarter section
 - ⊕ WC (witness corner)
- constructed rds
- ≡≡≡ 2 tracks associated with placer mine in sec. 35, gps'd 4/10/01



No warranty is made by the Bureau of Land Management for use of any of the data for purposes not intended by Bureau of Land Management.

